

FZ1600OL Fuze Outer Leg







Step 1

1





Push the beams onto the 1st leg frame lining up the beam holes with the M6 threaded holes on the leg.

Ensure the screen fixing points on the outer leg and cut out slots on the beams are facing inwards.









Please Note

5

If you have purchased a larger configuration of desk than the one shown please refer to the FZ1600IL instruction before proceeding with step 4



If you have purchased a sliding top system please refer to the sliding top bracket assembly instruction from this point onwards.



For ease of assembly Screen Brackets and Horizontal Cable Trays should be fitted before you proceed to Step 7.



Step 7

Place the desktop onto the assembled framework ensuring that the edges of the desktop finish parallel with the end of the leg frames.

The framework may be slightly out of square, if this happens loosen the fixing bolts in the beams and align correctly before re tightening the bolts.



or







Attach the remaining side of the desktops to the frame using the M6 x 60mm Connect Bolts.

Ensure that the bolt passes through both the leg frame and Spacer Block.







FZ1600IL Fuze Inner Leg







Back to Back Desk Assembly

Please Note

4

This assembly instruction follows on from step 3 on the outer leg assembly instruction FZ1600OL











Step 4







Push the next set of beams onto the inner leg frame lining up only the outer beam holes with the M6 threaded holes nearest the edge on the leg.

Ensure the cut out slots on the beams are facing inwards.







(11)

Step 11

Place the desktop onto the assembled framework ensuring that the edges of the desktop finish parallel with the end of the leg frames.

The framework may be slightly out of square, if this happens loosen the fixing bolts in the beams and align correctly before re tightening the bolts.



or



