

















ASSEMBLY INSTRUCTIONS

6905

| (1)CASTER | (2)BASE | (3)GASLIFT | (4)SEAT | | |
|---|--|--|--|---|--|
|  X5 |  X1 |  X1 |  | <h2>A</h2>  <p>Diagram A shows the chair back (6) being attached to the seat (4) and armrests (5). Screws (8)-1, (8)-2, and (8)-3 are used for assembly.</p> | <h2>B</h2>  <p>Diagram B shows the chair back (6) and armrests (5) being attached to the base (2) and seat (4). Screws (7) and (8)-1 are used for assembly.</p> |
| (5)ARMREST | (6)BACK | (7)MECHANISM | | | |
|  X2 |  |  | | <h2>D</h2>  <p>Diagram D shows the cable management system (D) being attached to the chair base.</p> | <h2>E</h2>  <p>Diagram E shows the final assembled chair.</p> |
| <p>(8) 1.  X4 6X20(MM)</p> <p>2.  X6 6X25(MM)</p> <p>3.  X2 8X25(MM)</p> <p>4.  X8</p> <p>5.  X1</p> | | | | | |